

V1.02.00 Build 0003 (Aug 2016)

Changes/New Features

- The trigger delay malfunction of Auxiliary Power output is fixed. The configured delay setting will be kept not be cleared to zero, after powering down the unit.
- The over voltage offset is modified. The over voltage offset is used in the over voltage detection. The over voltage offset is calibrated for better accuracy.
- The temperature sensors detection is improved. The temperature sensors for the heat sink, the onboard power capacitor and the main PCB is now monitoring periodically to check their work condition and send out warning if any failure is detected.
- Three warning messages are added to indicate the sensor error for the main PCB, the heat sink, and the onboard power capacitor.

V1.01.00 Build 0001 (Feb 2011)

First Production Release